



# 5100 Firmware Change List

---

## Scope

Firmware D0MU058 is applicable to all configurations 1.9TB and under of the 5100 ECO, PRO and MAX. The previous production release was based upon firmware D0MU045.

The following 5100 ECO, PRO and MAX configurations are being updated from previous firmware D0MU045 to D0MU058:

MTFDDAK480TBY, MTFDDAK960TBY, MTFDDAK1T9TBY, MTFDDAV480TBY  
MTFDDAV960TBY, MTFDDAV1T9TBY

MTFDDAK240TCB, MTFDDAK480TCB, MTFDDAK960TCB, MTFDDAK1T9TCB  
MTFDDAV240TCB, MTFDDAV480TCB, MTFDDAV960TCB, MTFDDAV1T9TCB

MTFDDAK240TCC, MTFDDAK480TCC, MTFDDAK960TCC, MTFDDAK1T9TCC

## Summary of Changes

Changes and improvements made in firmware D0MU058 over previous firmware D0MU045 are:

- General error handling and stability improvements
- Error handling improvements
- Improved command response times
- Improved compatibility with HBAs
- Improvements to asynchronous power loss handling
- Enhanced data integrity algorithms

Updating directly from all older firmware revisions is supported. However, please note that reverting to any firmware revision prior to D0MU058 is prevented after updating to this firmware version.