



# 5100 Firmware Change List

---

## Scope

Firmware D0MU414 is applicable to the 3.8TB configuration of the 5100 ECO and PRO. Firmware D0MU814 is applicable to the 7.6TB configuration of the 5100 ECO. Previous production releases were based either upon firmware D0MU412 or D0MU812 depending upon the drive configuration.

The following 5100 ECO and PRO configurations are being updated from previous firmware D0M412 to D0MU414:

MTFDDAK3T8TBY

MTFDDAK3T8TCB

The following 5100 ECO configuration is being updated from previous firmware D0MU812 to D0MU814:

MTFDDAK7T6TBY

## Summary of Changes

Changes and improvements made in firmware D0MU414 & D0MU814 over previous firmware D0MU412 and D0MU812 are:

- General error handling and stability improvements
- TRIM time performance improvement
- Enhanced data integrity algorithms

Updating directly from all older revisions is supported. However, please note that reverting to any firmware revision prior to D0MU402 or D0MU802 is prevented after updating to firmware D0MU414 and D0MU814.