



5200 Firmware Change List

Micron 5200 SATA SSD Family SKU vs Firmware Matrix

Drive SKU	Previous Firmware Version	New Firmware Version
All 5200 drive SKUs <= 2TB	D1MU004	D1MU008
5200 4TB ECO SKU	D1MU404	D1MU408
5200 4TB PRO SKU	D1MU505	D1MU508
5200 8TB ECO SKU	D1MU804	D1MU808

Affected Micron Part Numbers

Firmware D1MU0xx is applicable to all configurations 1.9TB and under.

ECO: MTFDDAK480TDC, MTFDDAK960TDC, MTFDDAK1T9TDC

PRO: MTFDDAK960TDD, MTFDDAK1T9TDD

MAX: MTFDDAK240TDN, MTFDDAK480TDN, MTFDDAK960TDN, MTFDDAK1T9TDN

Firmware D1MU4xx is applicable to ECO configurations of 3.8TB.

MTFDDAK3T8TDC

Firmware D1MU5xx is applicable to PRO configurations of 3.8TB.

MTFDDAK3T8TDD

Firmware D1MU8xx is applicable to ECO configurations of 7.6TB.

MTFDDAK7T6TDC

Special Requirements

Requires reboot/power cycle: No

FW downgrade possible: Yes

Summary of Changes

Changes and improvements made over previous versions are:

- Improvements to asynchronous power loss handling
- Improved command response times
- Improved compatibility with HBAs
- Improved performance consistency
- General stability improvements
- Error handling improvements
- Improved AMAC command handling
- Improved WRITE UNCORRECTABLE EXT handling on 3840GB and 7680GB drive SKUs